

RAJ ENGINEERS

ARCHITECTS, ENGINEERS, APPROVED VALUERS AND
STRUCTURAL ENGINEERS

Phone no. **9811129797**
49789617

Office: **H-34/35, 1st floor, Sector-3**
Rohini, Delhi-110085

Residence: A-3/228, Sec-5, Rohini, Delhi-85

RAJ KUMAR

B.Sc., B.Tech(civil) I.I.T.Delhi, M-Tech (Structure)
Govt. Regd. Approved Valuer CAT – I/396
Empanel SBI No. –CCO/CPM/VAL/99
Empanel PNB of ZO Delhi/Recovery
MCD Regd License No. E-1025
MCD Regd Structural Engineer No. SE-21
Fellow Member of I.I.T.Arb. No. F- 0555
Life Member of I.B.C. Membership No. ML-6627
Member of C.I.A. Council.
Member of The Institution of Engineers (India)
Membership No. : M- 1578744


Ref:- **RE/SSC/2023-24/JUL./022**

Dated : 26.07/2023

STRUCTURE SATABILITY CERTIFICATE

This is certified that the property at plot of Land bearing school at Sector- 3, at Rohini, Delhi , in residential area of school building known as **REMAL PUBLIC SCHOOL, situated at Pocket A- 2, Sector- 3, Rohini, Delhi- 110085**, belonging to **M/S REMAL PUBLIC SCHOOL Society, O/o A – 2, Sector- 3, Rohini, Delhi - 110085** , was inspected by me and found that the school building is constructed on RCC frame structure with RCC slab and structural parts of the entire school building has been designed on the basis of calculations and are considered safe in accordance with the permissible stresses slenderness ratio. The school building is three storied as per approved plan by D.D.A. The building is safe for the school purpose only .

Any Subsequent change from the existing building will be the responsibility of the Society/Owner (s)


RAJ KUMAR
STRUCTURE ENGINEER
GOVT. APPROVED VALUER
MCD Registration No. SE-21
H-34/35/3, 1st Floor, Sector-3, Rohini
Delhi-110085, (M) : 9811129797